1110



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety					
This section must be completed in its entirety	to constitute a v	alid maintenance pe	ermit. This permit	must be complete	
<u>prior</u> to performing maintenance activi			on of the maintena	nce activity.	
Date of Maintenance: 11-28-16 Reason		Vision of the second of the se			
Property Address: 12240 Panawa A				+ McDau	
Municipality: Stillwater ZIP: SS	Property Ide	entification Number:			
Maintenance Permit No: 123093 x 5364				ewer Service/L167	
Maintenance Performed	Tank Mea	surement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped	Liquid Level of	Liquid Level of Tank in			
☐ Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100				
\square Yes \square No (if no provide measurements)	The second secon	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Access used to remove septage: Maintena Were all covers securely replaced? Yes Is there evidence of tank leakage from a sepevidence of damaged, cracked, or structure 	□ No ptic, holding, pret	reatment or pump t	ank below the one	rating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed	?	191			
Tank #1 250 gal Tank #2	gal Pretreatmen	t tank gal	Pump Tank	gal	
5. Other information: List any troubleshooting,					
Manhole in landscaping	1flowers		,		
6. Location of septage disposal:	1	v la "W			