

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entire	ty to constitute a	alid maintenance	permit. This permit	must be complete	
prior to performing maintenance activ	ities and remain o	n-site for the dura	ation of the maintena	nce activity.	
Date of Maintenance: 11-30-16 Reason	on for Maintenance:	Rootin			
Property Address: 9651 68th St	CtN	Property Owner's	Name: Rober +	Proces	
Municipality: Stillwater ZIP:55	Property Id	entification Numbe	r:	1,000,1	
Maintenance Permit No: p 6534 125383				 ewer Service/L167	
Maintenance Performed	Tank Mea	surement (must b	e completed if tanks	NOT pumped)	
Tank(s) Pumped		Liquid Level of Tank in			
\square Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100				
\square Yes \square No (if no provide measurements			anks must be pumped		
 Were all covers securely replaced? Yes Is there evidence of tank leakage from a se evidence of damaged, cracked, or structure. 	ptic, holding pret	reatment or pump ntenance hole cove	tank below the oper ers?	ating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes 🖊 No	☐ Yes ♠No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed	?				
Tank #1 gal Tank #2	gal Pretreatment	tankg	al Pump Tank	gal	
5. Other information: List any troubleshooting To old for Munhale	, minor repairs co	nducted, tank safe	ty concerns, or other	gal r concerns.	
5. Location of septage disposal:					