

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must b	e completed in its entirety	to constitute a v	alid maintenance r	ormit This same	Landing A. P. C.
prior to perfe	orming maintenance activiti	es and remain o	n-site for the dura	tion of the	: must be complete
Date of Maintenance	: 10 - 25 - 16 Reason	for Maintenance	Posite for the dura	tion of the mainten	ance activity.
Municipality: ( W o	5766 lake and	101. PC.	Property Owner's N	lame: Jean S	anmicht.
marresparity.	Elmo ZIP:550	42 Property Id	entification Number	:	
Maintenance Permit	No:W4137X4930M	aintainer Name a	and License No. Pin	ky's Environmental !	Sewer Service/L1673
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
<ul><li>2. Were all covers se</li><li>3. Is there evidence</li></ul>	rove septage:  Maintenance curely replaced?  Yes of tank leakage from a septaged, cracked, or structural Tank  Septic/Holding Tank #1	No	reatment or numb	tank halamata	rating depth or
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?				
Tank #1 750	gal Tank #2 750 g	gal Pretreatment	tank ga	l Pump Tank	gal
5. Other information:	List any troubleshooting, n	ninor repairs co	nducted tank safet	V concerns or other	gal
System	two old for	man holes		y concerns, or other	er concerns.
6. Location of septage	disposal:				