

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a v	alid maintenance	permit. This permit	must be completed	
<u>prior</u> to performing maintenance activi	ties and remain o	n-site for the dura	ation of the maintena	nce activity	
Date of Maintenance: 11-17-16 Reason	for Maintenance:	10	atine		
Property Address: 7633 66th St. Municipality: Property ZIP:		Property Owner's	Name: John Fu	06	
Municipality: Prespinas ZIP:	Property Ide	entification Numbe	er:)	
Maintenance Permit No: 99672 F 3064	Maintainer Name a	and License No. Pi	nky's Environmental Se	ewer Service/L1673	
Maintenance Performed	Tank Mea	surement (must b	e completed if tanks	NOT pumped)	
Tank(s) Pumped	Liquid Level of	Liquid Level of Tank in			
Sludge and scum measured	III and the same of the same	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater				
 Were all covers securely replaced? Yes Is there evidence of tank leakage from a seq evidence of damaged, cracked, or structure 	otic, holding, pret	reatment or pump ntenance hole cov	o tank below the oper ers?	ating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ◀ No	☐ Yes 전 No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed	?				
Tank #1/500 gal Tank #2	gal Pretreatmen	t tank	gal Pump Tank	gal	
5. Other information: List any troubleshooting	minor repairs co			r concerns.	
6. Location of septage disposal:					