## Washington 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730 Subsurface Sewage Treatment System Maintenance P

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT **GOVERNMENT CENTER**

## Subsurface Sewage Treatment System Maintenance Permit

This section must be o	completed in its entirety t	o constitute a vali	d maintenance per	mit. This permit mu	ist be completed
prior to perforn	ning maintenance activitie	es and remain on-	site for the duratio	n of the maintenance	e activity.
Date of Maintenance: _	9/2/16 Reason f	or Maintenance: _	Routine)	(D. 1	)
Property Address: 16	133 18th St	5. <b>S</b> . Pr	operty Owner's Na	me: Janda Ni	permann
Water Ct Co	wix Beach ZIP: 550	U.2 Property Iden	tification Number:		
				c c : /104F	_
Maintenance Permit No	D: <u>W5393p3900</u> M	aintainer Name an	d License No. Meyer	r Sewer Service/ L913	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if r	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	nove septage: Maintenar	nce Hole 🗌 Other (e	nter authorization co	de)	
2. Were all covers see	curely replaced? Yes	□No			
3. Is there evidence of	of tank leakage from a sep aged, cracked, or structura	tic, holding, pretr	eatment or pump t tenance hole cove	tank below the operars?	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes No	☐ Yes ☐,No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \					gal
5. Other information	: List any troubleshooting	_ , minor repairs co	nducted, tank safe	ety concerns, or othe	r concerns.
			$\overline{}$		
			$\supset II$		
6. Location of septage	e disposal:	TY St.	Ken		