Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be c	ompleted in its entirety to	constitute a vali	d maintenance per	mit. This permit mu	ist be completed	
prior to perform	ning maintenance activitie	s and remain on-s	ite for the duratio	n of the maintenanc	e activity.	
Date of Maintenance: _	9/6/16 Reason fo	or Maintenance: _	ROUTINE			
Property Address: <u>17</u>	23 ZUINLAN AV	IE S PI	operty Owner's Na	me: BRIAN T	ROCHMAN	
Municipality: ST. CRO	DIX BEACH ZIP: 5504	Property Iden	tification Number:			
Maintenance Permit No	: <u>162959390</u> 7Ma	aintainer Name an	d License No. Meyer	r Sewer Service/ L915	5	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
Section 2015 According to the Control of the Contro	o provide measurements)	= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	ove septage: Maintenand	ce Hole 🗌 Other (e	nter authorization co	de)	-	
	curely replaced? 🕮 Yes 🗆					
3. Is there evidence of	of tank leakage from a sept ged, cracked, or structura	ic, holding, pretr	eatment or pump t tenance hole cover	tank below the operars?	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 🕅 No	☐ Yes XNo	☐ Yes 🕅 No		
	Septic/Holding Tank #2	☐ Yes XNo	☐ Yes ☑No	☐ Yes 🔼No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed?					
Tank #1 1 Cop gal Tank #2 1600 gal Pretreatment tank gal Pump Tank gal						
5. Other information	: List any troubleshooting,	minor repairs co	nducted, tank safe	ty concerns, or othe	er concerns.	
Cust	omer Dug 7	anks				
			^ /			
6. Location of septage	e disposal:	P 57	- Part			