

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety t	o constitute a vali	d maintenance pe	rmit. This permit mu	ist be completed
prior to perform	ming maintenance activiti	es and remain on-	site for the duration	on of the maintenanc	e activity.
Date of Maintenance: _	9/8/16 Reason f	for Maintenance: _	Routine		
Dura sutu Addrossi //	6601 5th St	Y) Pi	roperty Owner's Na	me: Mike Ear	twood)
Property Address: _//					
Municipality: Jake		43 Property Iden	tification Number:		
Maintenance Permit No	69098W3916 1851-1-7915 M	laintainer Name an	d License No. Meye	r Sewer Service/ L915	i
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if r	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
	nove septage: Maintenar		nter authorization co	ode)	<i>FO</i>
2. Were all covers see	curely replaced? Yes	□ NO	ant or nump	tank bolow the opera	ating depth or
3. Is there evidence of dama	of tank leakage from a sep aged, cracked, or structur	ally unsound main	tenance hole cove	rs?	ating depth of
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes JANO	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 7 gal Tank #2 gal Pretreatment tank gal Pump Tank gal					
5. Other information	: List any troubleshooting	, minor repairs co		ety concerns, or othe	r concerns.
1000		4			
6. Location of septage	e disposal:	o Stur			