

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety					
prior to perfor	ming maintenance activiti	ies and remain on-	site for the duration	on of the maintenand	ce activity.	
Date of Maintenance:	9/13/16 Reason	for Maintenance: _	Routine		Λ	
Property Address: 9	295 Meletare age Grovezip: 59	rRd P	roperty Owner's Na	mex Harey L	Jewisch)	
Property Address	Harris of	The second second	tifi aa tiaa Numbaru			
Municipality: <u>Colla</u>	ige / Xionelip: 53	Property Iden	tification Number:			
Maintenance Permit N	o: <u>f3695x4243</u> A	Maintainer Name an	d License No. Meye	r Sewer Service/ L91	5	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to I		Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
Yes No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or grea					f 25% or greater	
<ul><li>2. Were all covers se</li><li>3. Is there evidence</li></ul>	nove septage: Maintena curely replaced? Yes of tank leakage from a sep aged, cracked, or structur	□ No otic, holding, pretr	eatment or pump	tank below the oper	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☑No	☐ Yes No	☐ Yes ♠No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	<del>1</del> ?				
Tank #1 1500	gal Tank #2	gal Pretreatmen	t tankg	al Pump Tank	gal	
5. Other information	: List any troubleshooting	g, minor repairs co	nducted, tank safe	ety concerns, or othe	er concerns.	
	*		<del>}</del>			
6. Location of septag		-0 51)	/			