## Washington 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730 Subsurface Sewage Treatment System Maintenance P

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT **GOVERNMENT CENTER**

## Subsurface Sewage Treatment System Maintenance Permit

	I de la la continuation for	a constituto a vali	d maintenance ner	mit This permit mu	ist be completed
This section must be o	completed in its entirety to	o constitute a vali	u mamtenance per		a activity
<u>prior</u> to perforr	ning maintenance activitie	es and remain on-	site for the duratio	n of the maintenance	e activity.
Date of Maintenance: _	9/13/16 Reason for 890 Highlan	or Maintenance: _	Routine	100	6
Property Address: 5	890 Highlan	ds Pi	operty Owner's Na	me: Low Schi	dveiler
Municipality: Tak	e Elmo ZIP: 550	42 Property Iden	tification Number:		
	:22888/4244 M			Sewer Service/ L915	5
	Desfermed	Tank Measi	rement (must be	completed if tanks N	OT pumped)
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	ove septage: Maintenan	ce Hole 🗌 Other (e	nter authorization co	de)	
2. Were all covers see	curely replaced? Yes	□No			
3. Is there evidence of	of tank leakage from a sept ged, cracked, or structura	tic, holding, pretr	eatment or pump t tenance hole cover	ank below the operars?	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes ☐ No	☐ Yes No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1	gal Tank #2	gal Pretreatmen	t tankg		gal
5. Other information	: List any troubleshooting,	, minor repairs co	nducted, tank safe	ty concerns, or othe	er concerns.
	*				
-	170	0	<del>( )                                   </del>		
6. Location of septage	e disposal:	Still			