

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT **GOVERNMENT CENTER**

Subsurface Sewage Treatment System Maintenance Permit

	THE RESERVE TO A PROPERTY OF THE PARTY OF TH				- 4
This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
Property Address: 4021 OMAHA AVE. N. Property Owner's Name: ALLEN KROENING-					
Property Address: <u>40</u>	21 OMAHA AVA	<i>E. N</i> . Pr	operty Owner's Na	ne: <u>ALLEN K.R.C</u>	SENING-
Municipality: Baytown TwP ZIP: 55082 Property Identification Number:					
	:: C256/144252 Ma				logs
Manrechance reminers	e a got le l'a go				
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to b		Sludge + Scum / Liquid Level X 100			
	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
	nove septage: Maintenan		nter authorization co	de) Oligina	ego
2. Were all covers securely replaced? Yes No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes No	☐ Yes (A No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 1000 gal Tank #2 1000 gal Pretreatment tank gal Pump Tank gal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
Old System - House 1901					
/			ρ ()		
6. Location of septage disposal:					