

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety (to constitute a val	id maintenance pe	rmit. This permit m	ust be completed
prior to perfor	ming maintenance activiti	es and remain on-	site for the durati	on of the maintenand	ce activity.
Date of Maintenance:	9/19/16 Reason	for Maintenance: _	Routine)	
Property Address: <u>/</u>	3808 20th St	. <i>N</i> . P	roperty Owner's Na	ame: Mary	arland
Municipality: Sest e	Lakeland IIP: 550	82 Property Ider	tification Number:		
Maintenance Permit N	o: <u>r5123p4267</u> N	Maintainer Name an	d License No. Meye	er Sewer Service/ L91	5
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if	= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers set Is there evidence of 	nove septage: Maintenar curely replaced? X Yes of tank leakage from a sep aged, cracked, or structure	□ No otic, holding, pretr	eatment or pump	tank below the oper	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 🏿 No	☐ Yes 🏿 No	☐ Yes 🏚 No	
	Septic/Holding Tank #2	□ Yes 🕅 No	☐ Yes 🗖 No	☐ Yes 🎾 No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 1000	gal Tank #2 1000	_gal Pretreatmen	t tankg	al Pump Tank	gal
5. Other information	: List any troubleshooting	, minor repairs co	nducted, tank safe	ety concerns, or othe	r concerns.
	186				
6. Location of septage	e disposal:	WTP ST	. PAUD		