## Washington County

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a val	id maintenance pe	ermit. This permit m	ust be completed
	ming maintenance activiti			on of the maintenanc	ce activity.
Date of Maintenance:	9/20/16 Reason	for Maintenance: _	Routine		
Property Address: 82	282 27th St.	<u>n.</u> p	roperty Owner's Na	ame John 7	farusso
Municipality: Lake	Elmo ZIP: 550	Property Ider	itification Number:		
Maintenance Permit No	o: <u>n4604g4264</u> M	Naintainer Name an	d License No. Meye	er Sewer Service/ L915	5
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
The state of the s		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or grea					25% or greater
1. Access used to rem	nove septage: X Maintenai	nce Hole 🗌 Other (e	enter authorization co	ode)	
2. Were all covers see	curely replaced? Yes	□No		-	
3. Is there evidence of	of tank leakage from a sep aged, cracked, or structur	tic, holding, pretr			ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes ᡬÑò	☐ Yes No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 (500 gal Tank #2 gal Pretreatment tank gal Pump Tank gal					gal
5. Other information	: List any troubleshooting	, minor repairs co	nducted, tank safe	ety concerns, or othe	r concerns.
			$\bigcirc$		
-	20				
6. Location of septage	e disposal:	TY. STI	W		