

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
Date of Maintenance: 9/21/16 Reason for Maintenance: Routine					
Date of Maintenance. 1/2//6 Reason for Maintenance.					
Property Address: 8860 42nd St 11 Property Owner's Name: Enc Lambert					
Municipality: Lake Elmo ZIP: 55042 Property Identification Number:					
Maintenance Permit No: 14/263932 Maintainer Name and License No. Meyer Sewer Service/ L915					
Maintenance Permit No	5. <u>114/26 39 32</u> ma	ilitalilei Nalle ali	a License No. Meyer	Sewer Service, Exis	
Maintenar	nce Performed	Tank Meas	rement (must be c	ompleted if tanks NO	T pumped)
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Maintenance Hole  Other (enter authorization code)					
2. Were all covers securely replaced?   Yes □ No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 🕅 No	☐ Yes ⊠No	☐ Yes 🎗 No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?					
Tank #1 /250 gal Tank #2 gal Pretreatment tank gal Pump Tank gal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
Customer dig tank open					
6. Location of septage disposal: WTP St Rev/					