

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be complete						
<u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.						
Date of Maintenance: _	9/27/16 Reason fo	or Maintenance: _	ROUTINE		<u></u>	
Property Address: <u>/</u> 4	223 OAKGREEN	J CIR. E Pr	operty Owner's Nar	ne: GEORGE (	LEMENTS	
	ON ZIP: 5500				_	
	o: <u>f 8808 q 4388</u> Ma			Sewer Service/ L915	<u> </u>	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
☑ Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to b		Sludge + Scum / Liquid Level X 100				
	no provide measurements)	= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
<ol> <li>Were all covers securely replaced? Yes No</li> <li>Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?</li> </ol>						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes No	☐ Yes No	☐ Yes 🗖 No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	?		Ψ.		
Tank #1 / 2 0x2 gal Tank #2 gal Pretreatment tank gal Pump Tank					gal gal	
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.  3 feet dief doesn't went dieg						
6. Location of septag	e disposal: W - 1	1				