

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety				
prior to perfor	ming maintenance activit	ies and remain on-	site for the duratio	on of the maintenand	ce activity.
Date of Maintenance:	9/30/16 Reason	for Maintenance: _	Routine	)	
Property Address:	4727 70th S	r. S. P	roperty Owner's Na	me: SILKE SI	EPMANN
Municipality: DENM	MARK TWSPZIP: 550	)33 Property Iden	tification Number:		
	o: <u>C8336b4302</u>				5
Maintenar	nce Performed	Tank Meas	urement (must be	completed if tanks N	IOT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence	curely replaced? Yes of tank leakage from a selaged, cracked, or structure	ptic, holding, pretr	eatment or pump tenance hole cove	tank below the oper rs?	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 🕅 No	☐ Yes ☐ No	☐ Yes No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	d?			
Tank #1 \500 gal Tank #2 gal Pretreatment tank gal Pump Tank gal					
5. Other information	: List any troubleshooting	g, minor repairs co	nducted, tank safe	ety concerns, or othe	er concerns.
			2 ()		
6. Location of septage	e disposal:	to 9t.	(Alal)		