

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety					
<u>prior</u> to perfor	ming maintenance activit	ies and remain on-	site for the durati	on of the maintenanc	e activity.	
Date of Maintenance:		for Maintenance: _				
Property Address: _2	030 Wooderes	of dr P	roperty Owner's Na	ame: Don Sp	Jano	
Municipality:	11.00 71P: (S)	29 Property Iden	tification Number:			
	, ,					
Maintenance Permit N	o: <u>n</u> 3626,3933 1	Maintainer Name an	d License No. Meye	er Sewer Service/ L913		
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks NO	OT pumped)	
☑ Tank(s) Pumped		Liquid Level of T	Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in 7	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100						
☐ Yes ☐ No (if	Yes No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater					
3. Is there evidence	curely replaced? A Yes of tank leakage from a sep aged, cracked, or structur	ptic, holding, pretr	eatment or pump tenance hole cove	tank below the opera	ting depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ∑ No	☐ Yes XNo	☐ Yes 🐼 No		
	Septic/Holding Tank #2	☐ Yes KNo	☐ Yes 🔼 No	☐ Yes ☑No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	1 ?				
Tank #1 <u>/ OOO</u> gal Tank #2 <u>/ OOO</u> gal Pretreatment tank gal Pump Tank gal						
5. Other information	: List any troubleshooting	g, minor repairs co	nducted, tank safe	ety concerns, or other		
6. Location of septage	e disposal: W. /	/				