

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

		System	Location			
Address 6720	Cracklebo	erns "	Trail	Telephone Numb	per	
	nerej	State	_ ZIP	Property ID No./GEO C	ode	
Owner Acue	Gansmoe	Pumping Da	ate 9/7/	16		
Contractor						
Maintainer Boss Pump	ing .	MPCA Licen	se No. 1945	Telephone Numb	oer (651) 466-0800	
What was	done to the system?	t de la companie de l		Report Liquid Capacit	2. 1961 · 1961 · 1961 · 1962 · 1962 · 1963	
Tank(s) Pumped		ar a transfer	Tank 1:	Pumped Tank	2: Pumped	
Sludge and scum measured.			Tank 3:	Pumped Tank	4: Pumped	
Do tanks need to be pumped?			Total Gallons	Total Gallons Pumped: 2500+		
Yes No (If no provide measurements below)						
Visual Inspection (note any problems with the system): NOTE: This does not serve as a compliance inspection.						
	p.					
*Tank Measurements-Use Only If Tank(s) Were NOT Pumped						
Tank Length	in. X Tank Width	in. X Tan	k Depth	in. = Tank Volume (cu	bic inches)	
Tank Radius	in. X Tank Radius	in. X 3. 1	14 = Tank Volum	e (cubic inches)		
Tank Volume (cu. in.) / 231.01 = Liquid Capacity Gallons / Tank Depth in. = Gallons/Inch						
Sludge Level in. X Gallons Per Inch = Sludge Volume Gallons						
Scum Level	in. X Gallons Per Inch	= Scum	Volume	Gallons		
Sludge Volume	+ Scum Volume	= Total	Sludge and Scum V	olume Ga	illons	
Total Sludge and Scum Volume / Liquid Capacity = Percent Sludge and Scum in Tank %						
e.				following cond 1. The top of th	ne sludge layer is less than	
Scum Layer	T		- 15 1	hafflet or	the bottom of the outlet	
Effluent			Tank Depth measu from invert of outle	2. Total sludge	and scum volume is greate	
Sludge Layer		San activities and section	pipe to bottom of t	than 15 nercer	than 25 percent of the tank's liquid capacity.	
Simotime (A)	18	D:	ate Q-7-	4	Reset Form	