1122



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

prior to performing m	ted in its entirety aintenance activiti	to constitute a v ies and remain o	alid maintenance	permit. This permit	must be completed
Date of Maintenance: 12-20	>-/6 Reason	for Maintenance:	Partone	tion of the maintena	ance activity.
Property Address: 4855				Name: Chester	Martrix
Municipality: Lake Ely	uo ZIP550	Property Ide	entification Number	:	· Coch ic
Maintenance Permit No:					Sewer Service/L1673
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
Access used to remove sep Were all covers securely re Is there evidence of tank le evidence of damaged, cra	placed? Yes A	□ No ic, holding, pret	reatment or nump	tank below the one	rating depth or
-	Tank	Leaking Out	Leaking In	Cover Damage	
Septic/H	olding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Septic/H	olding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatr	nent Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Ta	nk	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septag	e were removed?				
Tank #1 / Suc gal Tank #2 gal Pretreatment tank gal Pump Tank					gal
Other information: List any	troubleshooting, i	minor repairs co	nducted, tank safe	ty concerns, or othe	er concerns.
6. Location of septage disposal:					