1102

Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a v	alid maintenance r	permit This permit	must be semplete	
<u>prior</u> to performing maintenance activit	ties and remain o	n-site for the dura	tion of the maintena	nust be complete	
Date of Maintenance: 12-7-16 Reason	for Maintenance:	Routine			
Property Address: 8991 Cakhill	Are Mc.	Property Owner's N	Name: Mark	windisch	
Municipality: Still Vato zip: 550	82 Property Ide	entification Number	:		
Maintenance Permit No: <u>U383755776</u>				ewer Service/L167	
Maintenance Performed	Tank Mea	surement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped	Liquid Level of Tank in				
\square Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100				
\square Yes \square No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater				
 Access used to remove septage: Maintena Were all covers securely replaced? Yes Is there evidence of tank leakage from a sep evidence of damaged, cracked, or structure cracked, or structure contact the second contact the second con	□ No tic, holding, pret	reatment or pump	tank below the oper	ating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed? Tank #1 /500 gal Tank #2		t tank	l D T		
			al Pump Tank	gal	
5. Other information: List any troubleshooting, Loudon't get to manho	4. Growel		ty concerns, or other	r concerns.	
				405	
6. Location of septage disposal:					