

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must b	e completed in its entiret	v to constitute a v	alid maintenance	pormit This servit		
prior to perf	orming maintenance activ	ities and remain o	n-site for the dur	permit. This permit i	nust be completed	
				ation of the maintenai	nce activity.	
Date of Maintenance	:: 19-16 Reason	n for Maintenance:	Routa			
Property Address: /	0780 St. Mar	ujs Dr	Property Owner's	Name: Lew F	a) mer	
Municipality:	· ·	Property Ide				
Maintenance Permit	No: p8079g5576					
Mainten	ance Performed	Tank Mea	surement (must b	pe completed if tanks I	NOT pumped)	
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank in			
☐ Sludge and scum	Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to						
☐ Yes ☐ No (it	f no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater					
3. Is there evidence	ecurely replaced? Yes of tank leakage from a sepaged, cracked, or structur	otic, holding, pret	reatment or pump stenance hole cov	p tank below the opera ers?	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 🗷 No	☐ Yes ② No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	\square Yes \square No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	?				
Tank #11250		gal Pretreatmen	t tank	gal Pump Tank	gal	
5. Other information	: List any troubleshooting	, minor repairs co	nducted, tank saf	ety concerns, or other	san	
				, and a suite	concerns.	
				The second		
6. Location of septage	e disposal:				3	