

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

RONMENT 1792

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its ent	irety to constitute a	valid maintenance	permit This permit r	much be seemed to	
<u>prior</u> to performing maintenance a	ctivities and remain	on-site for the dur	ation of the maintenar	nust be completed	
Date of Maintenance: 12-5-16 Re	eason for Maintenance	: Routin	A section of the maintenan	ice activity.	
Property Address: 10870 140	im St. M.	Property Owner's	Name: \Quin	\(uenn	
Municipality: ZIP:	55039 Property Ic	lentification Number	ar.	100101111	
Maintenance Permit No: h4864,548	Maintainer Name	and License No. Pi	nky's Environmental Se	wer Service/L1673	
Maintenance Performed	Tank Me	asurement (must b	e completed if tanks N	NOT pumped)	
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured	11	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measureme		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Is there evidence of tank leakage from a evidence of damaged, cracked, or strugent 	septic, holding, pret cturally unsound mai	treatment or pump ntenance hole cov	tank below the opera ers?	ating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	🔀 Yes 🗌 No	♠ Yes □ No	☐ Yes ☐ No		
Septic/Holding Tank #2	🛭 Yes 🗌 No	← Yes □ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were remo	ved?	777 7. 7. 7.			
Tank #1 750 gal Tank #2 750	gal Pretreatmen	t tank g	al Pump Tank	gal	
o. Other information: List any troubleshoot	ing, minor repairs co	nducted, tank safe	ety concerns, or other	concerns.	
. Location of septage disposal:					