

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

## Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety t				
	ning maintenance activitie				
	12-12-16 Reason f				
Property Address: 22	28 Itasca Ave	2 5, P	roperty Owner's Na	ame:	
Municipality: 57 Mar	y. Point ZIP:	Property Ider	tification Number:		
	: C630314074 M				03
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
	o provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers sec	ove septage: Maintenan curely replaced? Yes	No			
	f tank leakage from a sept ged, cracked, or structura				ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
,	Septic/Holding Tank #1	☐ Yes No	☐ Yes No	☐ Yes No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?				
Tank #1 1500	_ gal Tank #2	gal Pretreatmen	tankg	al Pump Tank	gal
	List any troubleshooting,				
	*				
6. Location of septage	disposal:				