

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety t	to constitute a val	id maintenance pe	ermit. This permit mu	ust be completed	
<u>prior</u> to perfor	ming maintenance activiti	es and remain on	site for the durati	on of the maintenance	e activity.	
Date of Maintenance:	2-3-17 Reason	for Maintenance:	Kes/	laint		
△ 5	DESK M	- // -		E. D.	20.00/	
Property Address:	DI Vane U	<u>// </u>	roperty Owner's Na	ame: Cric 19	permay	
Municipality:	E/ma ZIP:556	YC.Property Ider	ntification Number:			
Maintenance Permit No	1276C553X	, Naintainer Name an	d License No. Smil	ie's Sewer Service/L2	428	
				THE PROPERTY OF THE PROPERTY O		
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
\square Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers see Is there evidence of 	nove septage: Maintenar curely replaced? Yes [of tank leakage from a sep aged, cracked, or structura	□ No tic, holding, pretr	eatment or pump	tank below the opera	ting depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐No	☐ Yes ♠No	☐ Yes ☐No		
	Septic/Holding Tank #2	□ Yes 🗗 No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Tank #1 1500	of septage were removed gal Tank #2 1500: List any troubleshooting,	gal Pretreatmen	t tankg nducted, tank safe	al Pump Tankety concerns, or other	gal concerns.	
6. Location of septage disposal: Chisago land Agh						
			P			