

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety t	to constitute a val	id maintenance pe	rmit. This permit m	ust be completed	
prior to perfor	ming maintenance activiti	es and remain on-	site for the durati	on of the maintenan	ce activity.	
Date of Maintenance:	Nailin Reason	for Maintenance: _	Emerger	rcy/Rout	ine	
Property Address:	100 Jocelyn Ln	N P	roperty Owner's Na	me: Tony+Cinc	di Ranten	
Municipality: 5+114	vater zip:550	Property Ider	ntification Number:			
				: -1 - C C i / 1 2		
Maintenance Permit No	:: <u>+492455858</u>	iaintainer Name an	a License No. Smil	ie's Sewer Service/L2	.428	
Maintenar	nce Performed	Tank Meas	urement (must be	completed if tanks N	IOT pumped)	
X Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
100	tanks need to be pumped? Sludge + Scum / Liquid Level X 100					
☐ Yes ☐ No (if r	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater				
<ol> <li>Access used to remove septage:          Maintenance Hole Other (enter authorization code)          Pro 1978         </li> <li>Were all covers securely replaced?          Yes          No     </li> <li>Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?</li> </ol>						
*	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes →No	□ Yes No	☐ Yes XNo		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	?				
Tank #1 $1300$ gal Tank #2 gal Pretreatment tank gal Pump Tank gal						
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
replaced 4" outlet to drop box						
	Castiron	re	pair 'Cor	npiered		
6. Location of septage	e disposal: Metro		\	<b>.</b>		