

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety to	o constitute a val	id maintenance pe	ermit. This permit mu	ıst be completed
<u>prior</u> to perform  Date of Maintenance: _	ming maintenance activitie	es and remain on or Maintenance:	site for the duration	on of the maintenance	e activity.
Property Address: 13	906 St Crock	tol P	roperty Owner's Na	ame: MIKE 1	Spen
CILI	100	2		,	7
Municipality: 5/7/	water ZIP: 5500	Property Ider	tification Number:		
Maintenance Permit No	0: <u>84115 c 58 56</u> Ma	aintainer Name an	d License No. Smil	ie's Sewer Service/L2	428
Maintenan	ice Performed	Tank Meas	urement (must be	completed if tanks N	OT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	nove septage: Maintenand	ce Hole $\square$ Other (e	nter authorization co	ode)	
2. Were all covers sec	curely replaced? 🗸 🗡 es 🗆	□No			
3. Is there evidence of evidence of dama	of tank leakage from a sept ged, cracked, or structura	ic, holding, pretr Ily unsound main	eatment or pump tenance hole cove	tank below the operars?	ting depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?				
Tank #1 /200		tankg	al Pump Tank	gal	
	List any troubleshooting,				concerns.
	1992				
	v 1 1	-			
6. Location of septage	e disposal: Mox	0			