

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	lid maintenance p	ermit. This permit n	nust be completed	
<u>prior</u> to perfor	ming maintenance activit	ties and remain on	-site for the durat	ion of the maintenar	ice activity.	
Date of Maintenance:	/~/ Reason	for Maintenance:	Lou Ma	int		
Property Address: $\overline{2}$	6200 X	1 11		ame: Marcec	Olson	
Municipality: Fore	it 1 K ZIP: 550	25 Property Ide	ntification Number	:		
Maintenance Permit N	0:477Bg5852			lie's Sewer Service/L	2428	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater				
2. Were all covers se3. Is there evidence	nove septage: Maintena Curely replaced? Yes of tank leakage from a sepaged, cracked, or structur	\square No otic, holding, preti	eatment or pump	tank below the oper	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes No	☐ Yes ♠No	☐ Yes ੴNo		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons,	of septage were removed	1?		-		
Tank #1 1200 gal Tank #2 gal Pretreatment tank gal Pump Tank gal						
	: List any troubleshooting				r concerns.	
3		,	,	// /		
6. Location of septage	e disposal:	sago la	ud /	pply		