

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety t				
<u>prior</u> to perform	ning maintenance activition	es and remain on-	site for the duration	on of the maintenance	activity.
Date of Maintenance: 12-6-16 Reason for Maintenance: Routine					
Property Address: 23039 Perkins Ave N Property Owner's Name: Michael Cakagno					
Municipality: <u>Scan</u> e	10 a zip: 55073	Property Ider	tification Number:		_
Maintenance Permit No	: <u>e4348+5525</u> M	aintainer Name an	d License No. Smil	ie's Sewer Service/L24	28
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
☑ Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if r	= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
<ol> <li>Access used to remove septage: ⋈ Maintenance Hole □ Other (enter authorization code)</li> <li>Were all covers securely replaced? ⋈ Yes □ No</li> <li>Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?</li> </ol>					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 🏿 No	☐ Yes 🎾 No	☐ Yes 🖾No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	□ Yes 🖾 No	☐ Yes 🏿 No	☐ Yes 💢 No	
4. How many gallons	of septage were removed	?			
Tank #1 $1000$ gal Tank #2 gal Pretreatment tank gal Pump Tank $500$ gal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
W					
6. Location of septage disposal: Metro Waste					