

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
prior to perform	ning maintenance activiti	ies and remain on-	site for the duration	on of the maintenanc	ce activity.
Date of Maintenance:	12/2/16 Reason	for Maintenance: _	Routine		
Property Address: <u>/</u> 4	131 30th St.	7. P	roperty Owner's Na	ame: Chuck &	Buschoff
	Lakelandzip: 550				_ 00
Maintenance Permit No	: 27242 W 5196 N	Maintainer Name an	d License No. Meye	er Sewer Service/ L915	5
Maintenan	ce Performed	Tank Meas	urement (must be	completed if tanks N	OT pumped)
		Liquid Level of Tank in			
Tank(s) Pumped		Sludge Level in Tank in Scum Level in Tank in			
Sludge and scum measured		Sludge + Scum / Liquid Level X 100			
Do tanks need to be pumped?		= % Sludge & Scum Tanks must be pumped if 25% or greater			
Yes No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater					
<ol> <li>Were all covers securely replaced? Yes No</li> <li>Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?</li> </ol>					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes XNo	☐ Yes No	☐ Yes ☐No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	N.
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	1?			
Tank #1 1200 gal Tank #2 gal Pretreatment tank gal Pump Tank gal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
	1-	0 6:1	0.1		
6. Location of septage	e disposal:	r GT	ras		