

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed						
prior to perform	ning mainteņance activiti	es and remain on-	site for the duration	on of the maintenanc	e activity.	
Date of Maintonance:	12/8/16 Reason	for Maintenance:	Routhe			
Date of Maintenance	16 16 Keason	. I	7-00774	^	1 /	
Property Address:	480 Arcola Tr	<i>V</i> P	roperty Owner's Na	ime: Jodg V	GLASOK	
Municipality: St. Www.ferZIP: 55082 Property Identification Number:						
Maintenance Permit No: 40946 v 3938 Maintainer Name and License No. Meyer Sewer Service/ L915						
maintenance Permit No	40146 y 3770 "	Maintainer Hame an	a Electise No. Meye	T Server Service.		
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
☐ Tank(s) Pumped☐ Sludge and scum measured		Liquid Level of Tank in				
		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 2. Were all covers securely replaced? Yes \(\subsetention \) No 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes KNo	☐ Yes XNo	☐ Yes XNo		
	Septic/Holding Tank #2	☐ Yes X No	□ Yes 🗡 No	☐ Yes ⊠No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	1?				
Tank #1 170,000 gal Tank #2 (COCO) gal Pretreatment tank gal Pump Tank gal						
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
Dug tunks						
/			0 1			
6. Location of septage	e disposal: 117	P 5+	Hav 1			