

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entire	ety to constitute a val	id maintenance p	ermit. This permit m	ust be completed	
prior to performing maintenance act	ivities and remain on-	site for the durat	ion of the maintenand	e activity.	
Date of Maintenance: 12/9/16 Rea	son for Maintenance: _	ROUTINE			
Date of Maintenance: $\frac{12/9/16}{90^{+16}}$ Real Property Address: $\frac{12850}{90^{+16}}$	ST. S. P	roperty Owner's N	ame: <u>KEVIN</u> FJ	ERSTAD	
Municipality: DENMARIC TWSP ZIP: E					
Maintenance Permit No: 9828705209				5	
Maintenance Performed	Tank Meas	urement (must be	completed if tanks N	OT pumped)	
Tank(s) Pumped	Liquid Level of T	Liquid Level of Tank in			
Sludge and scum measured	Sludge Level in 7	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurement	nts) = % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
<ol> <li>Were all covers securely replaced?</li> <li>Is there evidence of tank leakage from a evidence of damaged, cracked, or structure.</li> </ol>	septic, holding, pretr	eatment or pump tenance hole cove	tank below the opera ers?	ating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ⋈No	☐ Yes KNo	☐ Yes മ No		
Septic/Holding Tank #2	☐ Yes ☐ No	$\square$ Yes $\square$ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were remo	oved?				
Tank #1 <u>/200</u> gal Tank #2	gal Pretreatmen	t tank	gal Pump Tank	gal	
5. Other information: List any troubleshoo	oting, minor repairs co	nducted, tank saf	ety concerns, or othe	r concerns.	