

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
Date of Maintenance: 11/4/16 Reason for Maintenance: ROUTINE					
Property Address: 13	928 21ST ST.	<u>N</u> P	roperty Owner's Na	me: MARSHA	SHOTLEY
Municipality: WEST LAKELAND ZIP: 55082 Property Identification Number:					
	:p2342 K 5872 M				5
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to b		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if r	= % Sludge & Scu	% Sludge & Scum Tanks must be pumped if 25% or greater			
	ove septage: Maintenar		nter authorization co	de)	
2. Were all covers securely replaced? $oximes$ Yes \Box No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
,	Tank	Leaking Out	Leaking In	Cover Damage	
15	Septic/Holding Tank #1	☐ Yes 风No	☐ Yes ☒ No	☐ Yes 🎾 No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 1000 gal Tank #2 gal Pretreatment tank gal Pump Tank gal					
5. Other information	: List any troubleshooting	, minor repairs co	nducted, tank safe	ty concerns, or oth	er concerns.
6. Location of septage disposal: ST. PAUL WTP					