Washington 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730 Subsurface Sewage Treatment System Maintenance P

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

Subsurface Sewage Treatment System Maintenance Permit

This section must be o	completed in its entirety to	constitute a val	d maintenance pe	rmit. This permit mu	ist be completed
prior to perform	ning maintenance activitie	s and remain on-	site for the duratio	on of the maintenanc	e activity.
Date of Maintenance:	11/7/16 Reason fo	or Maintenance:	ROUTINE	5	
Date of Maintenance	THE MEASON IN	o maintenance.	/(00///	C . 1	lan
Property Address: 15092 70th ST. S. Property Owner's Name: STEVEN WARD					
Municipality: DENM	ARK ZIP: 550	Property Iden	tification Number:		
Maintenance Permit No	o: <u>K9692K5133</u> Ma	aintainer Name an	d License No. Meye	r Sewer Service/ L915	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers securely replaced? Yes No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes XNo	☐ Yes X No	8
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?				
Tank #1 / \ gal Tank #2 gal Pretreatment tank gal Pump Tank gal					gal
5. Other information	: List any troubleshooting,	minor repairs co		ty concerns, or other	
6. Location of septage	e disposal:				