

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be co	ompleted in its entirety to	o constitute a val	id maintenance pe	rmit. This permit m	ust be completed	
prior to perform	ing maintenance activitie	es and remain on-	site for the duration	on of the maintenanc	ce activity.	
Date of Maintenance: 1	1/7/16 Reason fo	or Maintenance: _	ROUTINE	-		
Property Address: 8^{2}	384 STILLWA	TER BLUDP	roperty Owner's Na	ime: BERT 1	PRICE	
Municipality: <u>LAKE</u>	ELMO ZIP: 550	<u>火</u> プ Property Ider	tification Number:			
Maintenance Permit No:	<u>94528 j 5129</u> mi	aintainer Name an	d License No. Meye	r Sewer Service/ L91!	5	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
CONTRACTOR AND	provide measurements)	measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater				
3. Is there evidence of	urely replaced? X Yes C tank leakage from a sept ed, cracked, or structura	tic, holding, pretr	eatment or pump tenance hole cove	tank below the operars?	ating depth or	
-	Tank	Leaking Out	Leaking In	Cover Damage		
-	Septic/Holding Tank #1	☐ Yes No	☐ Yes X No	☐ Yes No		
}	Septic/Holding Tank #2	☐ Yes No	☐ Yes X No	☐ Yes No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of	f septage were removed?	•				
Tank #1 \ 005	gal Tank #2	⁹ gal Pretreatmen	tankg	al Pump Tank	gal	
5. Other information:	List any troubleshooting,	minor repairs co	nducted, tank safe	ty concerns, or othe	r concerns.	
		.()				