

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
prior to perform	ning maintenance activitie	s and remain on-	site for the duratio	on of the maintenanc	e activity.
Date of Maintenance:					
Property Address: //	503 77th St.	S. P	roperty Owner's Na	me: Marilen	Heschkel
77.	4 55	033	uici Ni Ni mah awa		
Property Address: 11503 17th St. S. Property Owner's Name: Marileyn Heschkel Municipality: Cattage Stave ZIP: 5503 Property Identification Number:					
Maintenance Permit No: <u>h 756955/59</u> Maintainer Name and License No. Meyer Sewer Service/ L915					
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
☐ Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if r	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
	ove septage: Maintenand		nter authorization co	de)	
2. Were all covers securely replaced? Yes No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
3	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes No	☐ Yes 团No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?					
Tank #1 /) gal Tank #2 gal Pretreatment tank gal Pump Tank gal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
Landscaping over tank					
6. Location of septage disposal:					