12119



## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

prior to performi	mpleted in its entirety ng maintenance activit					
Date of Maintenance: /-					ince activity.	
The second secon						
Property Address:					Sherrill	
Municipality: Hugo	ZIP: 55	>>> Property Ide	entification Number	:		
Maintenance Permit No:					ewer Service/L1673	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?			Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater				
Were all covers secure     Is there evidence of to evidence of damaged		tic, holding, pret	reatment or pump	tank below the opers?	ton k rating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
Sep	otic/Holding Tank #1	☐ Yes 🗷 No	☐ Yes 💆 No	☐ Yes ☐ No		
Sep	otic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pre	treatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pui	np Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of s	eptage were removed?					
Tank #1 1500 ga	al Tank #2	gal Pretreatmen	t tank ga	al Pump Tank	gal	
5. Other information: Lis	t any troubleshooting,	minor repairs co	nducted, tank safe	ty concerns, or other	er concerns.	
6. Location of septage dis	posal:					