

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must b	e completed in its entire	ty to constitute a v	alid maintenance	permit. This permit r	nust be complete	
Data of Main	orming maintenance activ	icies and remain o	n-site for the dur	ation of the maintenar	nce activity.	
	: 11-28-16 Reason					
Property Address:	3035 Valley Cre	ek TLS	Property Owner's	Name: Kristine	Barton	
Municipality:				er:		
Maintenance Permit	No:e 6715f 5350	Maintainer Name	nd License No. D	inlada Fasissassas I. C	_	
	C E 11.01.02.20	manitalite Name a	nd License No. P	inky's Environmental Se	wer Service/L1673	
Mainten	ance Performed	Tank Mea	surement (must l	pe completed if tanks i	NOT pumped)	
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank in			
☐ Sludge and scum measured			Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100						
Yes No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or grea					f 25% or greater	
2. Were all covers se3. Is there evidence	move septage: Mainten ecurely replaced? Yes of tank leakage from a se aged, cracked, or structu	□ No	reatment or num	n tank bolow the energy	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 🗗 No	☐ Yes 🎜 No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	1?				
Tank #1 /250	gal Tank #2	gal Pretreatment	tank	gal Pump Tank	gal	
5. Other information	: List any troubleshooting	, minor repairs co	nducted, tank saf	ety concerns, or other	concerns.	
	A STATE OF THE STA					
Location of septage	e disposal:				000	