

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety t	to constitute a val	id maintenance pe	rmit. This permit m	ust be completed	
<u>prior</u> to perfor	ning maintenance activiti	es and remain on-	site for the durati	on of the maintenand	e activity.	
Date of Maintenance: _	10/7/16 Reason	for Maintenance: _	ROUTINE			
	331 GOODVIEN				SON	
	GEGROVE ZIP: 550					
	, ,				_	
Maintenance Permit No	X4666 y 4317_ N	Maintainer Name an	d License No. Meye	er Sewer Service/ L915)	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or g					25% or greater	
3. Is there evidence of	curely replaced? Yes of tank leakage from a sep	tic, holding, pretr	eatment or pump tenance hole cove	tank below the opera	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes X No	☐ Yes XìNo	☐ Yes No		
	Septic/Holding Tank #2	☐ Yes 🎗 No	☐ Yes No	☐ Yes No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	1?				
Tank #1 \500 gal Tank #2 \cdot 000 gal Pretreatment tank gal Pump Tank gal						
5. Other information	: List any troubleshooting	_ , minor repairs co	nducted, tank safe	ety concerns, or othe	r concerns.	
			$\overline{}$			
		0				
6. Location of septage	e disposal:	TY Shil	NX.			