

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a va	lid maintenance pe	ermit. This permit r	nust be completed	
prior to performing maintenance activi	ties and remain on	-site for the durati	on of the maintenar	nce activity.	
Date of Maintenance: $10/7/16$ Reason	n for Maintenance: _	ROUTINE			
Property Address: 6360 GOODVIE	W BAYS	Property Owner's N	ame: JUSTIN	PROKOP	
Municipality: COTTAGE GROVE ZIP: 55					
Maintenance Permit No: w191464326	Maintainer Name ar	id License No. Meye	er Sewer Service/ L9	15	
Maintenance Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
X Tank(s) Pumped	Liquid Level of	Liquid Level of Tank in			
☐ Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements) = % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Access used to remove septage: Mainten. Were all covers securely replaced? Yes Is there evidence of tank leakage from a se evidence of damaged, cracked, or structu 	□ No ptic, holding, preto	reatment or pump	tank below the ope	rating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes 🗡 No	☐ Yes No	☐ Yes No		
Septic/Holding Tank #2	☐ Yes No	☐ Yes X No	☐ Yes No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were remove	d?				
Tank #1 \500gal Tank #2 \ 00	⇔ gal Pretreatmen	t tankg	al Pump Tank	gal	
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
		\cap			
6. Location of septage disposal:	of St.	. taul			