

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety		•	-	_	
<del></del> -	ming maintenance activit			on of the maintenar	ice activity.	
Date of Maintenance:	9/22/16 Reason	for Maintenance:	(outine)		<del></del>	
Property Address:	9855 53RDS	<u>r. N.</u> 1	Property Owner's N	ame: <u>REX CA7</u>	TANACH	
Municipality: LAK	EELMO ZIP: 55	04/3 Property Ide	ntification Number:			
	o: <u>w6862f4269</u> M	<del></del>			15	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to	be pumped?	Sludge + Scum / Liquid Level X 100				
$\square$ Yes $\square$ No (if	no provide measurements)	= % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence	curely replaced? Yes of tank leakage from a sep aged, cracked, or structur	otic, holding, preti			ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	□ Yes XNo	☐ Yes KNo	☐ Yes 🎵 No		
	Septic/Holding Tank #2	□ Yes ⊅CNo	☐ Yes <b>汉</b> No	☐ Yes 🗖 No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	?				
Tank #1 10000	gal Tank #2	gal Pretreatmen	t tankg	al Pump Tank	gal	
	: List any troubleshooting					
		<u> </u>				
6. Location of septage	e disposal:	0 S+ 1	اراد			