

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be o	completed in its entirety	to constitute a vali	d maintenance pe	rmit. This permit mu	ist be completed	
<u>prior</u> to perforr	ning maintenance activiti	es and remain on-	site for the duration	on of the maintenanc	e activity.	
Date of Maintenance: _	10/11/16 Reason 949 42NDS	for Maintenance: _	ROUTINE	B 10-C		
Property Address: <u>8</u>	949 42NDS	7. N P	roperty Owner's Na	ime: BARTGR	UNDHAUSE	
Municipality: 14 KE	ELMO ZIP: 550	Y/2 Property Iden	tification Number:		_	
Maintenance Permit No	:: <u>m/135g3936</u> M	Maintainer Name an	d License No. Meye	r Sewer Service/ L915		
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped Sludge and scum measured		Liquid Level of Tank in				
		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to b			Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25					25% or greater	
1. Access used to rem	nove septage: Maintena	nce Hole 🗌 Other (e	nter authorization co	ode)		
2. Were all covers sec	curely replaced? X Yes	□No				
3. Is there evidence of evidence of dama	of tank leakage from a sep aged, cracked, or structur	otic, holding, pretr ally unsound main	eatment or pump tenance hole cove	tank below the operars?	iting depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes No	☐ Yes No	☐ Yes No		
	Septic/Holding Tank #2	☐ Yes X No	☐ Yes No	☐ Yes No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were remove	d?				
Tank #1 156-5	gal Tank #2	gal Pretreatmen	t tankg	al Pump Tank	gal	
5. Other information	n: List any troubleshootin	g, minor repairs co	nducted, tank safe	ety concerns, or othe	r concerns.	
	i i		<u> </u>			
	L	10 0 0	()			
6 Location of septag	e disposal:	TV SIVU	1			