

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety t				
<u>prior</u> to perform	ning maintenance activiti	es and remain on-	site for the durati	on of the maintenanc	e activity.
Date of Maintenance: _	10/13/16 Reason t	for Maintenance: _	ROUTINE		
Property Address: 8	056 HILL TR.	N , Pi	operty Owner's Na	ame: TOM LINA	VELL
Municipality: LAKE	ELMO ZIP: 550	42 Property Iden	tification Number:		
Maintenance Permit No	: 9964104697 N	Naintainer Name an	d License No. Meye	er Sewer Service/ L915	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
☑ Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greate					25% or greater
 Were all covers securely replaced? Yes \(\sum \text{No} \) Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes XNo	☐ Yes KNo	☐ Yes 🐼 No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	1?			
Tank #1 16000 gal Tank #2 gal Pretreatment tank gal Pump Tank gal					
5. Other information	: List any troubleshooting	g, minor repairs co	nducted, tank saf	ety concerns, or othe	r concerns.
6. Location of septag	e disposal: $W-1$				