

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	y to constitute a vai	lid maintenance p	ermit. This permit n	nust be completed	
<u>prior</u> to perfo	rming maintenance activi		^			
Date of Maintenance:	7/8/1/6 Reason	n for Maintenance:	Koutine	೭		
Property Address: 🚅	724 Manne	ngaves.	roperty Owner's N	ame: <u>Maplawo</u>	vel Develop	
Municipality: Woo	alrivery ZIP:	5 /	ntification Number	•		
Maintenance Permit N	10: 2281421588	Maintainer Name ar	d License No. Mey	er Sewer Service/ L91	15	
Maintena	ince Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped		Liquid Level of 7	Liquid Level of Tank in			
\square Sludge and scum r	measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100						
☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater						
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
•	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes DNo	☐ Yes 🚺 No	☐ Yes 从No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were remove	d?				
Tank #1 /500	gal Tank #2	gal Pretreatmen	t tankg	gal Pump Tank	gal	
5. Other information	: Lişt any troubleshootin	g, minor repairs co	nducted, tank safe	ety concerns, or other	er concerns.	
Dug,	Manhale 7	Installed	Riser			
					-	
6. Location of septage	e disposal://TF	1- St Fa			·····	