

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	y to constitute a va	id maintenance pe	ermit. This permit m	ust be completed
<u>prior</u> to perfo	rming maintenance activi	ties and remain on	site for the durati	ion of the maintenan	ce activity.
Date of Maintenance:	7/19/16 Reason	n for Maintenance:	ROUTINE		
Property Address: /	4605 AFTON	BLVDS F	roperty Owner's N	ame: <u>KRIS KOP</u>	ITZKE
Municipality: AF		OO) Property iden			<u> </u>
Maintenance Permit N	0:018949 3470	Maintainer Name ar	d License No. Meye	er Sewer Service/ L91	5
Maintena	nce Renformed	Tank Meas	irement (must be	completed it tanks h	(OT pumped)
Tank(s) Pumped	•	Liquid Level of 1	ank in		
Sludge and scum r	neasured	Sludge Level in	ank in	Scum Level in Tank_	in
Do tanks need to	be pumped?	Sludge + Scum _	/ Liquid L	evel X 100	
☐ Yes ☐ No (if	no provide measurements	) = % Sludge & Sci	ım Taı	nks must be pumped i	f 25% or greater
<ul><li>2. Were all covers se</li><li>3. Is there evidence</li></ul>	nove septage: Amainten curely replaced? A Yes of tank leakage from a se aged, cracked, or structu	□ No eptic, holding, pretr	eatment or pump	tank below the opera	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 🜠 No	☐ Yes XNo	☐ Yes <b>X</b> No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were remove	d?			
Tank #1 / Dac gal Tank #2 gal Pretreatment tank gal Pump Tank					gal
	: List any troubleshootin		nducted, tank safe	ety concerns, or othe	r concerns.
6. Location of septage	e disposal:	1			