

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a val	id maintenance pe	ermit. This permit m	ust be completed	
<u>prior</u> to perfo	rming maintenance activi	ties and remain on	-site for the durati	ion of the maintenanc	e activity.	
Date of Maintenance:	7/19/16 Reason	for Maintenance:	Rocatine			
Property Address: //	358 Ramada	WeS. F	roperty Owner's N	ame: Sonja 1	Hennegan	
^ ^	71 .				1	
	oix Black ZIP:550	="				
Maintenance Permit N	10: <u>67541 y 3468</u>	Maintainer Name ar	id License No. Meye	er Sewer Service/ L915) 	
Maintenance Performed		Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence	ocurely replaced? Yes of tank leakage from a se aged, cracked, or structur	ptic, holding, preti	eatment or pump tenance hole cove	tank below the opera	iting depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 🗷No	☐ Yes Æ No	☐ Yes 🗷No		
	Septic/Holding Tank #2	☐ Yes 🗷 No	☐ Yes ☑ No	☐ Yes Æ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	1?				
Tank #1 / @ 600	gal Tank #2 1600) gal Pretreatmen	t tankg	al Pump Tank	gal	
	: List any troubleshooting				concerns.	
			<u> </u>	22		
<u> </u>	e		<u> </u>		· ·	
6. Location of septag	e disposal:	TP- St	Kul	<u> </u>		

Maintenance activities must be reported to the Department within 90 days.