

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	· · · · · · · · · · · · · · · · · · ·				
This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
<u>prior</u> to perforr	ning maintenance activitie	es and remain on-s	ite for the durati	on of the maintenance	e activity.
Date of Maintenance: _	10/18/16 Reason f	or Maintenance: 🖊	COUTINE		
Property Address: 8	862 MILITARY	ROAD Pr	operty Owner's Na	ame: JASON E	NGEL
Municipality: \	BURY ZIP: 55%	29 Property Iden	tification Number:		<u> </u>
Maintenance Permit No	:h120014717 M	— aintainer Name and	d License No. Meye	er Sewer Service/ L915	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
1-04 (9) (4)(4-1	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers securely replaced? Yes No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	1?			
Tank #1 10000 gal Tank #2 gal Pretreatment tank gal Pump Tank					gal
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
	,	0 0.	1		
6. Location of septage disposal:					