

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety t	o constitute a val	id maintenance pe	rmit. This permit r	nust be completed
<u>prior</u> to perfor	ming maintenance activition	es and remain on-	site for the duration	on of the maintena	nce activity.
Date of Maintenance:	7/	or Maintenance: _			4.
Property Address: 58	830 Hytruil As	e N P	roperty Owner's Na	me: James	Magan
Municipality:	Elmo ZIP: 5504	2 Property Iden	tification Number:	_	
Maintenance Permit No	0: 95062v0664 M	aintainer Name an	d License No.	leyer Sewar	
as a Maintenance Pentormed		Trank Meas	urement (musti per	लुम्भूमिद्दर्भाक्ष्मीङ	(/OIFPUINFEO)
☑ Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to b	e pumped?	11	·-	evel X 100	
☐ Yes ☐ No (if no provide measurements) = % Sludg			m Tan	ks must be pumped	if 25% or greater
 Were all covers securely replaced? Yes No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? Tank Leaking Out Leaking In Cover Damage					
•	Septic/Holding Tank #1	☐ Yes 🏖 No	☐ Yes 🌠 No	☐ Yes 🗷 No	
	Septic/Holding Fank#1	∐ Yes ÆNO	□ res 🕰 no		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	•
4. How many gallons	of septage were removed?	•			
		gal Pretreatment		l Pump Tank	gal gal
	List any troubleshooting,	minor repairs con Tenk	nducted, tank safe	ty concerns, or oth	er concerns.