

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed						
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.						
Date of Maintenance: _	10/20/16 Reason	for Maintenance: _	ROUTINE			
Property Address: $\underline{g}$	33 DAKGREE	N AVEN P	roperty Owner's Na	me: JENNIFER	STABENOW	
	LAKELAND ZIP: 550					
	:X073304728M				j	
maintenance remit no	NO 1330 1 180					
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to b		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if r	no provide measurements)	= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	nove septage: Maintena	nce Hole 🗌 Other (e	enter authorization co	de)		
	curely replaced? 🔀 Yes					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes X No	☐ Yes \\No	☐ Yes No		
	Septic/Holding Tank #2	☐ Yes XNo	☐ Yes ▼No	☐ Yes X No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	1?				
Tank #1 1500 gal Tank #2 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \						
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
		-0				
6. Location of septage disposal:						