

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

| This section must be o | completed in its entirety | to constitute a vali | d maintenance pe | rmit. This permit mu | ist be completed |
|---|---|--|-------------------------------------|-------------------------|------------------|
| prior to perform | ning maintenance activiti | es and remain on- | site for the duration | on of the maintenanc | e activity. |
| Date of Maintenance: _ | 10/34/16 Reason | for Maintenance: _ | ROUTINE | | |
| | 258 STAGECOA | | | me: HEIDI A | OFE |
| | | | | | 0212 |
| | LAKELAND ZIP: 550 | | | | _ |
| Maintenance Permit No | : 17589 4732 N | Naintainer Name an | d License No. Meye | r Sewer Service/ L915 | |
| | | | | | |
| Maintenance Performed | | Tank Measurement (must be completed if tanks NOT pumped) | | | |
| Tank(s) Pumped Sludge and scum measured | | Liquid Level of Tank in | | | |
| | | Sludge Level in Tank in Scum Level in Tank in | | | |
| Do tanks need to b | | Sludge + Scum / Liquid Level X 100 | | | |
| Yes No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or grea | | | | | 25% or greater |
| 3. Is there evidence of | curely replaced? Yes of tank leakage from a sep ged, cracked, or structur | otic, holding, pretr | eatment or pump enance hole cove | tank below the operars? | iting depth or |
| | Tank | Leaking Out | Leaking In | Cover Damage | |
| | Septic/Holding Tank #1 | ☐ Yes 🕅 Yo | ☐ Yes 🎗 No | ☐ Yes No | |
| | Septic/Holding Tank #2 | ☐ Yes 🛭 No | ☐ Yes No | ☐ Yes No | |
| | Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| | Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| 4. How many gallons | of septage were removed | d? | | | |
| Tank #1 1500 | gal Tank #2 \ \ | gal Pretreatmen | t tankg | al Pump Tank | gal |
| 5. Other information | : List any troubleshooting | g, minor repairs co | nducted, tank safe | ety concerns, or othe | r concerns. |
| | | | | | |
| | - dienosali | with | я | | |
| 6. Location of septag | e disposat. | //X / / · | | | |