

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be o	completed in its entirety to	constitute a vali	d maintenance per	rmit. This permit mu	st be completed
prior to perform	ning maintenance activitie	s and remain on-s	site for the duratio	on of the maintenance	e activity.
	10/26/16 Reason fo				
Property Address: 8	682 JAMACA	AVEN Pr	operty Owner's Na	me: JIM DRO	OST
	NT ZIP: 5508				
					
Maintenance Permit No	: <u>b 944004751</u> Ma	anitamer Name and	a Electise No. Meye	T Server Services 22:10	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped?		Liquid Level of Tank in			
		Sludge Level in Tank in Scum Level in Tank in			
		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if r	no provide measurements)	= % Sludge & Scu	m Tan	ks must be pumped if	25% or greater
3. Is there evidence of	curely replaced? Yes Confirmed	tic, holding, pretr	eatment or pump tenance hole cove	tank below the opera rs?	ting depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 //000m	- 1 10 (00	gal Pretreatmen	t tank <i>500</i> g	al Pump Tank	gal
	gal Tank #2 500	541			
5. Other information	gal Tank #2 500 a: List any troubleshooting	, minor repairs co	nducted, tank safe	ety concerns, or otne	r concerns.