

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entired	y to constitute a val	id maintenance pe	ermit. This permit m	ust be completed	
prior to performing maintenance activ	rities and remain on-	site for the durati	ion of the maintenan	ce activity.	
Date of Maintenance: $10/27/16$ Reason	on for Maintenance: _	ROUTINE			
Property Address: 3623 OAKGREE	N AVE N P	roperty Owner's N	ame: JOHN H	ECK	
Municipality: <u>STILLWATER</u> ZIP: <u>55</u>					
Maintenance Permit No: <u>S 2458g 4759</u>	Maintainer Name an	d License No. Meye	er Sewer Service/ L91	5	
Maintenance Performed	Tank Meas	urement (must be	completed if tanks N	OT pumped)	
X-Tank(s) Pumped	Liquid Level of 7	Liquid Level of Tank in			
☐ Sludge and scum measured	Sludge Level in -	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurement	s) = % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence of tank leakage from a sevidence of damaged, cracked, or struct	urally unsound main	tenance hole cove	ers?	ating depth of	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☑No	☐ Yes 🌂 No	☐ Yes KNo		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were remov	ed?				
Tank #1 1200 gal Tank #2	gal Pretreatmen	t tankg	gal Pump Tank	gal	
5. Other information: List any troubleshooti	ng, minor repairs co	nducted, tank safe	ety concerns, or othe	r concerns.	
6. Location of septage disposal:	P 5+1				